



INFRARED INSPECTION REPORT

February 13, 2015

Companies Unlimited

1401 Brand St.
Los Angeles, CA 90028

Contact: Ron McKinney



An Introduction to Infrared Inspection

When installed correctly and operated within their ratings, electrical systems are incredibly reliable and can provide years of uninterrupted service without any troubles. When problems do occur it is because of some sort of error in the system such as overloads, short circuits, poor connections or misapplied components (not designed for the particular installation). A common symptom of these types of errors is overheating. As all electrical components have temperature limits, this overheating can rather quickly lead to destruction. The magnitude of the over temperature can give a good idea as to how much longer the component(s) might survive.

Infrared inspection utilizes an infrared (heat detecting) camera to quickly and safely survey equipment and locate temperature anomalies invisible to the naked eye. Any anomaly found is further investigated to pinpoint the likely cause of the problem so that recommended corrective actions can be implemented. It is important to note that infrared inspections should only be conducted while the facility is in operation. Otherwise, there will be little if any heating of the equipment being examined and potential problems will be missed.

When examining temperature anomalies, we are not just looking for absolute temperature extremes, we are also interested in relative temperature. For example, a circuit breaker may have several poles, each carrying the same amount of current. We see that one of the poles is significantly hotter than the others but not necessarily over limit. As this is an anomaly, this peaks our interest so we will do additional testing to sort it out.

The Basic Procedure:

- Note the type of equipment being examined and its identification,
- Remove covers to expose the current carrying components,
- Scan the equipment for thermal anomalies,
- With each anomaly found, determine the likely cause by visual and metered examination,
- Save images showing the anomaly and document all other test results as applicable,
- Create a report showing the anomalies and the recommended corrective actions.

In short, infrared inspection is a unique method of observing equipment condition during normal operation. It is safe, efficient and effective. It can detect anomalies which, if left unchecked, could cause costly damage and downtime, not to mention more dramatic troubles. By performing a routine infrared inspection in addition to regular preventive maintenance, your control over your system increases, surprises reduce and you can get on with production.

Glossary

Amps: 1. A unit of electrical flow; 2. The rating of an electrical equipments flow carrying capacity.

Anomaly: Something different, abnormal, peculiar.

CB: An abbreviation for Circuit Breaker.

Circuit Breaker: A circuit control and protection device used to monitor and interrupt excessive flow of an electrical circuit. It consists of a switch and current monitor usually encased in a common housing. When excessive current is detected, the current monitor causes the switch to open.

Delta T: Refers to a difference in temperature. In our case, it refers to the difference between the reference and the hot spot measurement.

FS: An abbreviation for Fused Switch.

Fuse: A circuit protection device used to monitor and interrupt excessive flow of an electrical circuit. The fuse is put in line with the circuit and will open the circuit when the current exceeds its design rating.

Fused Switch (Fused SW): A circuit control and protection device used to monitor and interrupt excessive flow of an electrical circuit. It consists of a switch and fuses in a common enclosure. The switch only acts as a control for the user by opening and closing the circuit, while the fuses monitor the current and open when excessive current flows through the circuit.

Infrared (IR): A particular energy radiated from all objects. It is not visible to the naked eye, but using specialized equipment, can be detected and reveals object temperature.

MV Drop: An abbreviation for Millivolt-drop or 1/1000 of a volt. We measure MV Drop across certain devices to determine the possible location of a problem. A voltage drop across a device creates heat.

PANEL: A common electrical distribution enclosure containing various circuit breakers.

PMI: Abbreviation: 1. "Predictive Maintenance Inspection" 2. "Preventive Maintenance Inspection"

Predictive Maintenance Inspection: Techniques intended to detect anomalies in equipment while in operation. The purpose is to locate problems before failure so corrective actions can be scheduled to resolve the difficulty.

Preventive Maintenance Inspection: Techniques intended to keep equipment in good operating condition through cleaning, lubricating, torquing, visual inspection, etc. It is performed while the equipment is removed from service.

Reference: As used in these documents, reference refers to a temperature reading used to compare to a "hot spot". The reference will commonly be the ambient temperature of the components environment but it may also be an adjacent component deemed useful for comparison.

SWB: An abbreviation for Switchboard.

Switchboard: A large electrical distribution cabinet containing various switches and/or circuit breakers.

T Ambient: Stands for temperature ambient which is the measured ambient temperature at the time of the scan.

Transformer: An electrical conversion device used to raise or lower voltage (pressure) of an electrical system. Commonly used in commercial and industrial facilities to convert voltage for panels and machinery which require a different voltage than is available.

Voltage or Volts: A unit of electrical pressure.

XFRM: An abbreviation for Transformer.

INSPECTION REPORT - Equipment/Component List (Master)

(Items requiring attention are highlighted in "Red")

Customer/Facility: Companies Unlimited

Scan Date: Friday, February 13, 2015

IR Tech: Joe Smith

Location	Equipment ID	Component ID	Type	Rpt #	Priority	Trouble Summary
Building 100 Electrical Room	Main Service Switchboard	Overall Assembly				
Building 100 Electrical Room	Main Service	Service Main	CB			
Building 100 Electrical Room	Main Service	Unit #114 - House	CB			
Building 100 Electrical Room	Main Service	Unit #100 - Jalisco	CB			
Building 100 Electrical Room	Main Service	Unit #104 - Cal Fruit	CB			
Building 100 Electrical Room	Main Service	Unit #109	CB			
Building 100 Electrical Room	Main Service	Unit #102	CB	1	Medium	Overheated terminal/wire
Building 100 Electrical Room	Main Service	Unit #106	CB	2	Low	Overheating terminals
Building 100 Electrical Room	Main Service	Unit #110	CB			
Building 100 Electrical Room	Main Service	Unit #113 - Perricone Citrus	CB			
Building 100 Janitorial Room	Panel H1A	Overall Assembly				
Building 100 Janitorial Room	Panel H1A	Cir #21	CB	3	Low	Elevated Temp
Building 100 Janitorial Room	Panel H1A	Cir #35	CB	4	Low	Elevated Temp
Building 100 Janitorial Room	Panel H1A	Cir #38,40,42	CB	5	High	Overheating Connection
Building 100 Janitorial Room	Panel L1A	Overall Assembly				
Building 100 Janitorial Room	Panel L1A	Cir #19	CB	6	Medium	Bad Termination
Building 100 Janitorial Room	Panel L1A	Cir #10	CB	7	Low	Overheating Connection
Building 100 Janitorial Room	Panel L1B	Overall Assembly				
Building 100 Janitorial Room	Panel L1A-Sub (No Identification)	Overall Assembly				
Building 100 Janitorial Room	Transformer (No Identification)	Overall Assembly				
Building 200 Electrical Room	Main Service Switchboard	Overall Assembly				
Building 200 Electrical Room	Main Service	Service Main	CB			
Building 200 Electrical Room	Main Service	Unit #200 Helman Panel-A	CB			
Building 200 Electrical Room	Main Service	Unit #201 Helman Panel-B	CB			
Building 200 Electrical Room	Main Service	Unit #203	CB			
Building 200 Electrical Room	Main Service	Unit #204 Archies	CB			
Building 200 Electrical Room	Main Service	Unit #207 Coast	CB			
Building 200 Electrical Room	Main Service	Unit #208 Coast	CB			
Building 200 Electrical Room	Main Service	Unit #210	CB			
Building 200 Electrical Room	Main Service	Unit #211	CB			
Building 200 Electrical Room	Main Service	Unit #213 Olympic Refers	CB			
Building 200 Electrical Room	Main Service	Unit #214	CB			
Building 200 Electrical Room	Main Service	Unit #215 Olympic Refers	CB			
Building 200 Electrical Room	Main Service	Unit #217 Olympic Refers	CB			
Building 200 Electrical Room	Main Service	Unit #218	CB			
Building 200 Electrical Room	Main Service	Unit #219 Southland	CB			
Building 200 Electrical Room	Main Service	Unit #221 Morita	CB			
Building 200 Electrical Room	Main Service	Unit #222 Nut House	CB			
Building 200 Electrical Room	Main Service	Unit #223 Eagle Panel PC	CB			
Building 200 Electrical Room	Main Service	Unit #224 Eagle Panel LA	CB			
Building 200 Janitorial Room	Panel (No Identification)	Overall Assembly				
Building 200 Janitorial Room	Panel #212 "House Panel"	Overall Assembly				
Building 200 Janitorial Room	Panel #212-4 "House Sub-Panel"	Overall Assembly				
Building 200 Janitorial Room	Transformer (No Identification)	Overall Assembly	Trans	8	Medium	Corroded Lugs
Building 300 Electrical Room	Main Service Switchboard	Overall Assembly				
Building 300 Electrical Room	Main Service	Service Main				
Building 300 Electrical Room	Main Service	House				
Building 300 Electrical Room	Main Service	Unit #313 Choumas				

INSPECTION REPORT - Equipment/Component List (Master)

(Items requiring attention are highlighted in "Red")

Customer/Facility: Companies Unlimited

Scan Date: Friday, February 13, 2015

IR Tech: Joe Smith

Location	Equipment ID	Component ID	Type	Rpt #	Priority	Trouble Summary
Building 300 Electrical Room	Main Service	Unit #316 Season				
Building 300 Electrical Room	Main Service	Unit #317				
Building 300 Electrical Room	Main Service	Unit #318 Season				
Building 300 Electrical Room	Main Service	Unit #322 I&T				
Building 300 Electrical Room	Main Service	Unit #324				
Building 300 Electrical Room	Main Service	Unit #325 Davalan				
Building 300 Electrical Room	Main Service	Unit #304 Valley				
Building 300 Electrical Room	Main Service	Unit #305 Valley				
Building 300 Electrical Room	Main Service	Unit #306 Valley				
Building 300 Electrical Room	Main Service	Unit #310 Valley				
Building 300 Electrical Room	Main Service	Unit #307 Valley	CB	9	Medium	Elevated Temp
Building 300 Electrical Room	Main Service	Unit #311				
Building 300 Janitorial Room	Panel (No Identification)	Overall Assembly				
Building 300 Janitorial Room	Panel Suite 312+360	Overall Assembly				
Building 300 Janitorial Room	Panel Sub Suite 312+360	Overall Assembly				
Building 300 Janitorial Room	Transformer (No Identification)	Overall Assembly				
Building 400 Electrical Room	Main Service Switchboard	Overall Assembly				
Building 400 Electrical Room	Main Service	Service Main				
Building 400 Electrical Room	Main Service	Unit #401				
Building 400 Electrical Room	Main Service	Unit #402				
Building 400 Electrical Room	Main Service	Unit #404				
Building 400 Electrical Room	Main Service	Unit #403 Coast Citrus				
Building 400 Electrical Room	Main Service	Unit #408 Giumarra				
Building 400 Electrical Room	Main Service	Unit #400 House				
Building 400 Electrical Room	Main Service	Unit #409 Giumarra				
Building 400 Electrical Room	Main Service	Unit #410				
Building 400 Electrical Room	Main Service	Unit #406 Umina				
Building 400 Electrical Room	Main Service	Unit #407				
Building 400 Janitorial Room	Panel (No Identification)	Overall Assembly				
Building 400 Janitorial Room	Panel (No Identification)	Overall Assembly				
Building 400 Janitorial Room	Transformer (No Identification)	Overall Assembly				
Building 500 Electrical Room	Main Service Switchboard	Overall Assembly				
Building 500 Electrical Room	Main Service	Service Main				
Building 500 Electrical Room	Main Service	Unit #500 House				
Building 500 Electrical Room	Main Service	Unit #500				
Building 500 Electrical Room	Main Service	Unit #511 American Produce				
Building 500 Electrical Room	Main Service	Unit #512				
Building 500 Electrical Room	Main Service	Unit #513				
Building 500 Electrical Room	Main Service	Unit #502 Banana Co.				
Building 500 Electrical Room	Main Service	Unit #503 Banana Co.				
Building 500 Electrical Room	Main Service	Unit #507 Ogawa				
Building 500 Electrical Room	Main Service	Unit #505 Brostoff				
Building 500 Electrical Room	Main Service	Unit #508 Ogawa				
Building 500 Electrical Room	Main Service	Unit #514 American Produce				
Building 500 Janitorial Room	Panel (No Identification)	Overall Assembly				
Building 500 Janitorial Room	Panel L5A	Overall Assembly				
Building 500 Janitorial Room	Panel L5A	Main CB	CB	10	High	Overheating Connection
Building 500 Janitorial Room	Transformer (No Identification)	Overall Assembly				

INSPECTION REPORT - Equipment/Component List (Master)

(Items requiring attention are highlighted in "Red")

Customer/Facility: Companies Unlimited

Scan Date: Friday, February 13, 2015 **IR Tech:** Joe Smith

Location	Equipment ID	Component ID	Type	Rpt #	Priority	Trouble Summary
Building 500 Janitorial Room	Panel Joes Deli	Overall Assembly				
Building 500 Janitorial Room	Transformer (No Identification)	Overall Assembly				

INSPECTION REPORT - Equipment Voltage

Customer/Facility: Companies Unlimited

Scan Date: 2/13/2015

IR Tech: Joe Smith

[illegible]

TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 100 Electrical Room		
Equip. ID: Main Service	Make/Model: ITE FJ63B200	Report #: 1
Component ID: Unit #102		Priority *: Medium
Trouble: Overheated terminal/wire		



Observations and Recommendations:

Top left lug connection has overheated. Also, the wire insulation at that connection has swollen and been damaged. Recommend replacing the circuit breaker and wire. This may require a shut down of the service so will need to be coordinated appropriately.

Temperature Data	
Hot Spot:	
Reference:	
Delta T:	

Environmental Data	
T Ambient:	23.00°C
Humidity:	25%

Electrical Data (if applicable)	
Line 1:	
Line 2:	
Line 3:	



Left Image #: IR_0111	Camera/Lens: T420/25mm	Right Image #: DC_0112
------------------------------	------------------------	-------------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

--

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	

TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 100 Electrical Room		
Equip. ID: Main Service	Make/Model: ITE FJ63B200	Report #: 2
Component ID: Unit #106		Priority *: Low
Trouble: Overheating terminals		


Observations and Recommendations:

Appears to be localized heating on both the line and load terminals on the left hand pole. Suspect it may be only loose connection so recommend torquing. If no connection errors found please measure voltage drop and report results for further handling.

Temperature Data		
Hot Spot:	33.00°C	91.40°F
Reference:	29.40°C	84.92°F
Delta T:	3.60°C	6.48°F

Environmental Data	
T Ambient:	23.00°C
Humidity:	25%

Electrical Data (if applicable)		
Line 1:	66.0 A	
Line 2:	65.0 A	
Line 3:	68.0 A	



Left Image #: IR_0119	Camera/Lens: T420/25mm	Right Image #: DC_0120
------------------------------	------------------------	-------------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

--

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	



TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 100 Janitorial Room		
Equip. ID: Panel H1A	Report #: 3	
Component ID: Cir #21	Priority *: Low	
Trouble: Elevated Temp		

Observations and Recommendations:

Connection at elevated temperature. Two wires are terminated in the same lug which can cause poor connection. Recommend verification of loading and, if acceptable, splicing conductors to single pig tail and re-terminate to breaker.

Temperature Data			Environmental Data		Electrical Data (if applicable)		
Hot Spot:	43.10°C	109.58°F	T Ambient:	24.00°C	Line 1:	15.2 A	
Reference:	37.00°C	98.60°F	Humidity:	45%	Line 2:		
Delta T:	6.10°C	10.98°F			Line 3:		



Left Image #: IR_0129	Camera/Lens: T420/25mm	Right Image #: DC_0130
------------------------------	------------------------	-------------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

--

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	

*Priority: **High** = Failure imminent. Immediate correction required. **Medium** = Eventual failure likely. Correct at next down time. **Low** = Mild concern. Monitor and address when convenient.


TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 100 Janitorial Room		Report #: 4 Priority *: Low
Equip. ID: Panel H1A		
Component ID: Cir #35		
Trouble: Elevated Temp		

Observations and Recommendations:

Connection at elevated temperature. Appears to be localized at the lug. Recommend disconnecting and re-terminating the conductor.

Temperature Data			Environmental Data		Electrical Data (if applicable)	
Hot Spot:	38.70°C	101.66°F	T Ambient:	24.00°C	Line 1:	7.3 A
Reference:	35.70°C	96.26°F	Humidity:	45%	Line 2:	
Delta T:	3.00°C	5.40°F			Line 3:	



Left Image #: IR_0135	Camera/Lens: T420/25mm	Right Image #: DC_0136
------------------------------	------------------------	-------------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	

*Priority: **High** = Failure imminent. Immediate correction required. **Medium** = Eventual failure likely. Correct at next down time. **Low** = Mild concern. Monitor and address when convenient.



TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 100 Janitorial Room		
Equip. ID: Panel H1A	Make/Model: ITE E43B040	Report #: 5
Component ID: Cir #38,40,42	Priority *: High	
Trouble: Overheating Connection		

Observations and Recommendations:

Center load terminal is overheating, in fact all load connections appear elevated so suspect poor connections. Recommend re-terminating each load conductor and re-test with spot thermometer.

Temperature Data			Environmental Data		Electrical Data (if applicable)		
Hot Spot:	63.10°C	145.58°F	T Ambient:	24.00°C	Line 1:	7.8 A	
Reference:	30.60°C	87.08°F	Humidity:	45%	Line 2:	13.8 A	
Delta T:	32.50°C	58.50°F			Line 3:	13.4 A	



Left Image #: IR_0143	Camera/Lens: T420/25mm	Right Image #: DC_0144
------------------------------	------------------------	-------------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

--

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	



TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 100 Janitorial Room		
Equip. ID: Panel L1A	Report #: 6	
Component ID: Cir #19	Priority *: Medium	
Trouble: Bad Termination		

Observations and Recommendations:

Connection at elevated temperature. Termination does not include all strands of conductor. Recommend re-termination.

Temperature Data			Environmental Data		Electrical Data (if applicable)	
Hot Spot:	44.30°C	111.74°F	T Ambient:	24.00°C	Line 1:	5.6 A
Reference:	34.10°C	93.38°F	Humidity:	45%	Line 2:	
Delta T:	10.20°C	18.36°F			Line 3:	



Left Image #: IR_0147	Camera/Lens: T420/25mm	Right Image #: DC_0148
------------------------------	------------------------	-------------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

--

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	

*Priority: **High** = Failure imminent. Immediate correction required. **Medium** = Eventual failure likely. Correct at next down time. **Low** = Mild concern. Monitor and address when convenient.

TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 100 Janitorial Room		Report #: 7 Priority *: Low
Equip. ID: Panel L1A		
Component ID: Cir #10		
Trouble: Overheating Connection		



Observations and Recommendations:

Connection at elevated temperature. Appears to be localized at the lug. Recommend disconnecting and re-terminating the conductor.

Temperature Data		
Hot Spot:	39.40°C	102.92°F
Reference:	34.60°C	94.28°F
Delta T:	4.80°C	8.64°F

Environmental Data	
T Ambient:	24.00°C
Humidity:	45%

Electrical Data (if applicable)		
Line 1:	11.8 A	
Line 2:		
Line 3:		



Left Image #: IR_0153	Camera/Lens: T420/25mm	Right Image #: DC_0154
------------------------------	------------------------	-------------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	

*Priority: **High** = Failure imminent. Immediate correction required. **Medium** = Eventual failure likely. Correct at next down time. **Low** = Mild concern. Monitor and address when convenient.


TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 200 Janitorial Room		Report #: 8 Priority *: Medium
Equip. ID: Transformer (No Identification)		
Component ID: Overall Assembly		
Trouble: Corroded Lugs		

Observations and Recommendations:

Wiring connections are all extremely corroded. Recommend replacing all lugs, cutting away damaged wiring and re-terminating.

Temperature Data		Environmental Data		Electrical Data (if applicable)	
Hot Spot:		T Ambient:	21.00°C	Line 1:	
Reference:		Humidity:	23%	Line 2:	
Delta T:				Line 3:	



Left Image #: 84420	Camera/Lens: T420/25mm	Right Image #: 84425
----------------------------	------------------------	-----------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

--

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	

*Priority: **High** = Failure imminent. Immediate correction required. **Medium** = Eventual failure likely. Correct at next down time. **Low** = Mild concern. Monitor and address when convenient.

TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 300 Electrical Room		
Equip. ID: Main Service	Make/Model: ITE FJ63B200	Report #: 9
Component ID: Unit #307 Valley		Priority *: Medium
Trouble: Elevated Temp		


Observations and Recommendations:

Line side terminals are at slightly elevated temperatures. Recommend re-torquing connections. This work should be done during a shut down or while using proper PPE.

Temperature Data		
Hot Spot:	36.70°C	98.06°F
Reference:	27.80°C	82.04°F
Delta T:	8.90°C	16.02°F

Environmental Data	
T Ambient:	21.00°C
Humidity:	55%

Electrical Data (if applicable)		
Line 1:	85.0 A	
Line 2:	90.0 A	
Line 3:	95.0 A	



Left Image #: IR_0207	Camera/Lens: T420/25mm	Right Image #: DC_0208
------------------------------	------------------------	-------------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	

TROUBLE REPORT

Customer: Companies Unlimited	IR Tech: Joe Smith	Scan Date: 2/13/15
Area: Building 500 Janitorial Room		
Equip. ID: Panel L5A	Make/Model: ITE E43B100	Report #: 10
Component ID: Main CB		Priority *: High
Trouble: Overheating Connection		



Observations and Recommendations:

Line #1 Connection at elevated temperature. Appears to be localized at the lug. Recommend disconnecting and re-terminating the conductor.

Temperature Data		
Hot Spot:	45.00°C	113.00°F
Reference:	29.00°C	84.20°F
Delta T:	16.00°C	28.80°F

Environmental Data	
T Ambient:	21.00°C
Humidity:	55%

Electrical Data (if applicable)		
Line 1:	14.3 A	
Line 2:	12.0 A	
Line 3:	12.0 A	



Left Image #: IR_0219	Camera/Lens: T420/25mm	Right Image #: DC_0220
------------------------------	------------------------	-------------------------------

REPAIR REPORT

Repair Date:	
Electrician:	

Repair Notes: (If other than recommended repairs)

--

RESCAN REPORT

Rescan Date:	
IR Tech:	
Image #:	
Hot Spot:	
Reference:	
Delta T:	
Pass/Fail:	

*Priority: **High** = Failure imminent. Immediate correction required. **Medium** = Eventual failure likely. Correct at next down time. **Low** = Mild concern. Monitor and address when convenient.

INSPECTION REPORT - Trouble Summary

Customer/Facility: Companies Unlimited

Scan Date: 2/13/2015

IR Tech: Joe Smith

[illegible]